

TopsWorks 2018 SP2 | What's new

Release: September 2018

This release includes several improvements and bug fixes:

DPS-SPR #	Type	Description
2339	BUG	GEO-Export stops at part with FormingTool
2557	BUG	GeoExport hangs when TopsWorks punching features with contour transfer Single stroke are present
2560	BUG	Hole of hole wizard is incorrectly recognized as thread
0160	BUG	Performance increase when saving the contour attributes
2444	BUG	Bend table cannot be inserted, if configuration name doesn't contain "SM_FLAT_PATTERN"
2563	BUG	Wrong position or crash at FormingTool

FR = Feature Request