

TopsWorks 2016 SP2 | What's new

Release: 13.07.2016

This release includes several improvements and bug fixes:

DPS- SPR #	Typ	Beschreibung
2426	BUG	Crash of the AddIn in this model
2427	BUG	Progress bar dialog not fully represented, if Windows scaling is not 100%
2437	BUG	Can not insert Bend table (SOLIDWORKS 2014) ¹
2434	BUG	Bending is not recognized if it is created by "Move Face".
374	BUG	Contour attributes are incorrectly read or associated with the false contours.
0035	BUG	Extension of the documentation.
2440	BUG	SOLIDWORKS crash at the GeoExport, if the option "Save contour transfer" is enabled. ¹
1036	BUG	For sheet metal parts consider/set rolling direction (Incorrect value in the GEO for "allow turning")
2390	BUG	TopsWorks stops when insert the bend parameters
2441	BUG	No message if no material is selected when you insert the bend parameters.
2444	BUG	Bend table cannot be inserted if the configuration contains no SM_FLAT_PATTERN in the name ¹
2397	BUG	Error 1 by "Insert bend parameters" in this part

FR = Feature Request

¹ Prevent crash of TopsWorks. DPS-SPR is not completed. SPR submitted to SOLIDWORKS.